Statement of Deficiencies	**(X1) Provider/Supplier/CLIA Identification Number**	**(X3) Date Survey Completed**
	55C0001059	05/12/2026
Name of Provider or Supplier	**Street Address, City, State**	
Fort Sutter Surgery Center, A Ca Limited Partnership	2801 K Street, Suite 525, Sacramento, CA	

For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.

(X4) ID Prefix Tag	**Summary Statement of Deficiencies** (Each deficiency should be preceded by full regulatory or LSC identifying information)
K0223	Doors with Self-Closing Devices CFR(s): NFPA 101 Doors with Self-Closing Devices Doors required to be self-closing are permitted to be held open by a release device complying with 7.2.1.8.2 that automatically closes all such doors throughout the smoke compartment, entire facility, and all stair enclosure doors upon activation of: * Required manual fire alarm system, and * Local smoke detectors designed to detect smoke passing through the opening or a required smoke detection system; and * Automatic sprinkler system, if installed; and * Loss of power 20.2.2.4, 20.2.2.5, 21.2.2.4, 21.2.2.5 This STANDARD is not met as evidenced by: Based on observation and interview, the facility failed to maintain the doors equipped with self-closing devices. This was evidenced by a door that failed to latch when tested. This affected all patients and could result in the spread of fire or smoke in the event of a fire. Findings: During a tour of the facility and interview with Staff on 5/12/26, the doors were tested. At 10:47 a.m., the door to the room identified as GI 1 failed to latch when tested. The door was equipped with a self-closing device and was held open by a magnetic hold

	open device tied to the Fire Alam system. Upon interview, the Administrator stated that their door vendor was onsite and they would look at the door.