Statement of Deficiencies	**(X1) Provider/Supplier/CLIA Identification Number**	**(X3) Date Survey Completed**
	034525	08/07/2018
Name of Provider or Supplier	**Street Address, City, State**	
Saguaro Rehabilitation And Aquatic Therapy, Llc	305 North Plaza Drive, Apache Junction, AZ	

For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.

(X4) ID Prefix Tag	**Summary Statement of Deficiencies** (Each deficiency should be preceded by full regulatory or LSC identifying information)
I0574	SAFETY AND COMFORT OF PATIENTS CFR(s): 485.62(a)(3) A fire alarm system with local (in-house) capability must be functional, and where power is generated by electricity, an alternate power source with automatic triggering must be present. This STANDARD is not met as evidenced by: Based on observations during tour, and staff interviews, it was determined the CORF failed to require that their fire alarm system (Smoke detectors) mounted in various areas of the facility were completely assembled and completely functional within the facility. Failing to ensure that the smoke detectors were intact and completely functional, poses a high potential risk to the health and safety of patients in preventing harm from the spread of fire, if patients and staff cannot be warned of smoke created from an unwarranted situation. Findings include: Observation on tour on both 8/1/18 and 8/2/18, revealed that three smoke detectors were located in various locations within the facility that were only the outer shell of the smoke detector. There were no covers, no batteries attached and or a visible hardwiring smoke detector mechanism present. The Executive Director confirmed on 8/1/18 and 8/2/18 both that the items identified above were missing for each smoke detector.