Statement of Deficiencies	**(X1) Provider/Supplier/CLIA Identification Number**	**(X3) Date Survey Completed**
	01C0001010	01/03/2024
Name of Provider or Supplier	**Street Address, City, State**	
The Southern Alabama Surgery Center, Llc	2800 Ross Clark Circle, Suite 3, Dothan, AL	

For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.

(X4) ID Prefix Tag	**Summary Statement of Deficiencies** (Each deficiency should be preceded by full regulatory or LSC identifying information)
K0325	Alcohol Based Hand Rub Dispenser (ABHR) CFR(s): NFPA 101 Alcohol Based Hand Rub Dispenser (ABHR) ABHRs are protected in accordance with 8.7.3.1, unless all conditions are met: o Corridor is at least 6 feet wide. o Maximum individual dispenser capacity is 0.32 gallons (0.53 gallons in suites) of fluid and 18 ounces of Level 1 aerosols. o Dispensers shall have a minimum of 4-foot horizontal spacing. o Not more than an aggregate of 10 gallons of fluid or 1135 ounces of aerosol are used in a single smoke compartment outside a storage cabinet, excluding one individual dispenser per room. o Storage in a single smoke compartment greater than 5 gallons complies with NFPA 30. o Dispensers are not installed within 1 inch of an ignition source. o If floor is carpeted, the building is fully sprinkler protected. o ABHR does not exceed 95% alcohol. o Operation of the dispenser shall comply with Section 20.3.2.6(11) or 21.3.2.6(11). o ABHR is protected against inappropriate access. 21.3.2.6, 8.7.3.1, CFR 416.44 This STANDARD is not met as evidenced by: Based on observation, the facility failed to install Alcohol-Based Hand-Rub (ABHR) Dispensers per the requirements of: 2012 NFPA 101, 21.3.2.6 (8)

	This deficiency affects 1 of 12 Operating Rooms. Findings include: During a tour of the facility, the surveyor observed two ABHR Dispensers mounted 8” directly above two different light switches (ignition sources) in Operating Room 4. A member of maintenance staff was present when this deficiency was identified. .