Statement of Deficiencies	**(X1) Provider/Supplier/CLIA Identification Number**	**(X3) Date Survey Completed**
	054549	09/26/2018
Name of Provider or Supplier	**Street Address, City, State**	
Valley Corf Inc	18425 Burbank Blvd Suite 520, Tarzana, CA	

For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.

(X4) ID Prefix Tag	**Summary Statement of Deficiencies** (Each deficiency should be preceded by full regulatory or LSC identifying information)
I0572	SAFETY AND COMFORT OF PATIENTS CFR(s): 485.62(a)(1) Applicable Federal, State, and local building, fire and safety codes must be met. This STANDARD is not met as evidenced by: Based on observation, interview, and record review, the facility failed to follow State and fire and safety codes for fire extinguisher maintenance. This failure had the potential to place the patients and staff at risk for fire hazards. Findings: On 9/26/18 at 4:05 p.m., there was one fire extinguisher observed mounted on the: 1. interior wall of the occupational therapy (OT) room 2. hallway wall in between the OT and physical therapy (PT) room, and 3. wall adjacent to the Administrator's office On 9/26/18 at 4:10, during concurrent observation and interview, the facility Administrator stated that fire extinguishers were checked quarterly. The Administrator acknowledged that three of three fire extinguishers did not have documented evidence that it was checked quarterly. A review of the facility's undated policy and procedure titled, "Location of Exit Signs,

	Alarm Systems, and Fire Fighting Equipment," indicated that multi-purpose fire extinguishers are visibly located in several places throughout the facility in accordance with fire department recommendations. It also indicated that all staff members will be trained in the use of these extinguishers (as directed by other procedures in this section) and the extinguishers shall be tested. According to the California Code of Regulations, Title 8, Section 6151, portable fire extinguishers shall be visually inspected monthly.