Statement of Deficiencies	**(X1) Provider/Supplier/CLIA Identification Number**	**(X3) Date Survey Completed**
	01G011	08/17/2022
Name of Provider or Supplier	**Street Address, City, State**	
Rainbow Omega, Inc,	202 Hope Drive, Eastaboga, AL	

For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.

(X4) ID Prefix Tag	**Summary Statement of Deficiencies** (Each deficiency should be preceded by full regulatory or LSC identifying information)
E0000	K3 Building: 0101 K6 Plan Approval: 2006 K7 Survey Under: 2012 Existing K8 ICF/IID Small Generator: One Diesel, Katolight 125 kW (installed 2007, with remote maual stop station) FACP: Simplex 4010 (installed 2007) Locking Devices: 15 Second Delayed Egress (all doors except kitchen exterior door) Smoke Detection: Corridor Beds: 16 Census:15 Type of Structure: 2006 one story unprotected wood frame, Type V(000). The facility has a complete automatic sprinkler system with a sprinkler pit. The facility is surveyed under impractical to evacuate. During a routine recertification survey conducted on this date, the facility was found to be in compliance with 42 CFR 483.475 - Emergency Preparedness for ICF/IID facilities, as observed by the LS Surveyor while accompanied by facility personnel.