

Statement of Deficiencies	(X1) Provider/Supplier/CLIA Identification Number 010006	(X3) Date Survey Completed 07/15/2010
Name of Provider or Supplier North Alabama Medical Center	Street Address, City, State 1701 Veterans Drive, Florence, AL	
For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.		

(X4) ID Prefix Tag	Summary Statement of Deficiencies (Each deficiency should be preceded by full regulatory or LSC identifying information)
K0076	<p>LIFE SAFETY CODE STANDARD CFR(s): NFPA 101</p> <p>Medical gas storage and administration areas are protected in accordance with NFPA 99, Standards for Health Care Facilities. (a) Oxygen storage locations of greater than 3,000 cu.ft. are enclosed by a one-hour separation. (b) Locations for supply systems of greater than 3,000 cu.ft. are vented to the outside. NFPA 99 4.3.1.1.2, 19.3.2.4</p> <p>This STANDARD is not met as evidenced by: The facility failed to provide proper storage of oxygen cylinders. Findings include: A) During the survey, appropriate signage was not provided, no smoking sign was displaced in room, or on the door as you entered. CGA G-4, 4.1.10, and 1999 NFPA 99, 4-3.5.2.2(b)2 and 4-5.5.2.2(b)2 Full and empty cylinders shall be stored separately, with appropriate signage.</p>