Statement of Deficiencies	**(X1) Provider/Supplier/CLIA Identification Number**	**(X3) Date Survey Completed**
	55C0001059	04/10/2019
Name of Provider or Supplier	**Street Address, City, State**	
Fort Sutter Surgery Center, A Ca Limited Partnership	2801 K Street, Suite 525, Sacramento, CA	

For information on the provider's plan to correct this deficiency, please contact the provider or the state survey agency.

(X4) ID Prefix Tag	**Summary Statement of Deficiencies** (Each deficiency should be preceded by full regulatory or LSC identifying information)
K0000	K3 BUILDING: 01 K6 PLAN APPROVAL: 1986 K7 SURVEY UNDER: 2012 EXISTING STRUCTURE TYPE: FIVE STORY AND BASEMENT, CONSTRUCTION TYPE 1 (332), FULLY SPRINKLERED. The following reflects the findings of the California Department of Public Health, during a recertification Life Safety Code survey. The findings are in accordance with 42 Code of Federal Regulations (CFR) §416.44(b)(c)(f), National Fire Protection Association (NFPA) 101 - Life Safety Code, 2012 Edition, and NFPA 99 - Health Care Facilities Code, 2012 Edition. Representing the California Department of Public Health: 32973 Census: 37